

Arrows show the direction of non-contact stormwater drainage. Barns are labeled as shown and the enclosed feed bins are located adjacent to the barns. A fresh water pond is located west of the barns and appears clear. There No discharge was observed at the time of inspection on 05-24-11.